

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2026

Submitted Date:

03/02/2026

Document Number:

719001484

FIELD INSPECTION FORM

Loc ID: 334038 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10755
Name of Operator: MORNINGSTAR OPERATING LLC
Address: 400 W 7TH ST
City: FORT WORTH State: TX Zip: 76102

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
McDonough, Corey		corey.mcdonough@state.co.us	
Kittinger, Eric		ekittinger@mspartner.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262009	WELL	PR	07/09/2002	CBM	067-08670	DUELL 32-6 5-1	PR
293766	WELL	PR	11/29/2007	CBM	067-09450	DUELL 32-6 5-3	PR

General Comment:

Inspection Report Summary
On 3/2/26 I Inspector Charles Garcia conducted an on-site inspection.
Location: DUELL 32-6 5-1, DUELL 32-6 5-3
Operator: MORNINGSTAR OPERATING LLC
API#: 007-08670
API#: 067-09450
County: LA PLATA
All prior CA's still stand.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS LABELS AND PLACARDS SUN DAMAGED		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	505-333-4869 911 EMERGENCY		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	PRODUCED WATER TANKS HOG WIRE		
Corrective Action:		Date:	
Equipment:			
Type: Other			corrective date
	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Flow Line			
	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment			
	# 6		
Comment:	3 TELEMETRY EQUIPMENT 2 ELECTRICAL PANELS 1 CHEMICAL INJECTION CONTAINER WITH SPILL PREVENTION		
Corrective Action:		Date:	
Type: Bird Protectors			
	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run			
	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	DOMESTIC TAP		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	2 ELECTRIC PANELS IN FRONT OF PRODUCED WATER TANKS HAVE BEEN REMOVED EXPOSED WIRING IN BOTH LOCATIONS SEE LOCATION PICTURES		
Corrective Action:	Operate and maintain equipment to ensure stray current and static discharge does not constitute a hazard" rule 608.d. If equipment is not returned to service it should be abandoned per 1000 series rules by either removing or cutting off below grade.		Date: 03/09/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	PBV STEEL		37.050900,-107.518200
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms


Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:



Inspected Facilities

Facility ID: 262009 Type: WELL API Number: 067-08670 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 09/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 293766 Type: WELL API Number: 067-09450 Status: PR Insp. Status: PR

Producing Well

Comment:	SHARED LOCATION WITH DUELL 32-6 5-1	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 09/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Fail					
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: EAST SIDE OF LOCATION CHECK DAMS FAILING CAUSING DEEP RUTS FROM STORMWATER EROSION SEE LOCATION PICTURES

Corrective Action: Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f. (2)C

Date: 05/09/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001485	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465896