

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458


Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



1. Well sign

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



2. Access road.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



3. Pad entrance and gate.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



4. Wellhead and flow line.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



5. Well cellar and bradenhead.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458


Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



6. CP test point.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



7. Reclamation vegetation.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458


Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



8. Well pad and reclamation vegetaion looking south.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



9. Interim reclamation and location fence.

Inspection Photos  
Kinder Morgan – HE #3  
API # 05-083-06458

Inspector Name: James Blair. Inspection Date: 02/27/2026  
Inspection Doc #: 721100180



10. Reclamation vegetaion.