

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2026

Submitted Date:

03/03/2026

Document Number:

721100180

FIELD INSPECTION FORM

Loc ID 313540 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LLC
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections
Blair, Jamie		jamie.blair@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224393	WELL	PR	03/06/2018	CO2	083-06458	MCELMO DOME UNIT 35-38-19 HE #3	PR

General Comment:

At 5:45 PM on Friday, February 27, 2028 southwest compliance inspector Jamie Blair performed a compliance inspection on Kinder Morgan well HE-3. No Corrective actions were identified.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Well sign at entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-882-5522, emergency 911.

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: 4 strand barbed wire and t post fence. Gate open.

Corrective Action:

Date:

Equipment:

corrective date

Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	"CP Test Point" White tube with red cap where flow line goes into ground.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	30 ft long, 3" stainless.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	well cellar is dry		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224393 Type: WELL API Number: 083-06458 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100181	photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467050