

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2026

Submitted Date:

03/03/2026

Document Number:

719001491

**FIELD INSPECTION FORM**

Loc ID: 326679 Inspector Name: GARCIA, CHARLES On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262344	WELL	PR	01/10/2002	CBM	067-08679	GEARHART 01-06 2	PR

**General Comment:**

Inspection Report Summary  
On 3/3/26 I Inspector Charles Garcia conducted an on-site inspection.  
Location: GEARHART 01-06 #2  
Operator: Simcoe LLC  
API#: 067-08679  
County: LaPlata  
All prior CA's still stand.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE970-		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-247-6916 911 EMERGENCY		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	OTHER		
Comment:	COMPRESSOR SOUND WALLS		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	OIL LEAK ON COMPRESSOR ENGINE IMPACTED SOIL AROUND ENGINE SKID AND SOUTH SIDE OF SOUND WALL SEE LOCATION PICTURES		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND COMPRESSOR rule 1002.f		Date: 03/10/2026
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:

Type: Ancillary equipment	# 2	
Comment:	TELEMETRY EQUIPMENT LUBE OIL CONTAINER WITH SPILL PREVENTION FOR COMPRESSOR	
Corrective Action:		Date:
Type: Flow Line	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.239700,-107.674000
Comment:	21 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 262344 Type: WELL API Number: 067-08679 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 08/20/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001492	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467634</a>