

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2026

Submitted Date:

03/04/2026

Document Number:

698708445

**FIELD INSPECTION FORM**

Loc ID 307594 Inspector Name: Serna, Abe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Beardslee, Tom		tom.beardslee@state.co.us	
,	719-846-7898	cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217876	WELL	SI	12/01/2024	CBM	071-06655	LORENCITO 4-10-34-66	SI

**General Comment:**

"This is a field audit of the scout card, related documents and the location."

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

		#		corrective date
Type: Deadman # & Marked		# 1		
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run		# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:			Date:	
Type: Prime Mover		# 1		
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment		# 1		
Comment:				
Corrective Action:			Date:	
Type: Progressive Cavity		# 1		
Comment:				
Corrective Action:			Date:	
Type: Vertical Separator		# 1		
Comment:				
Corrective Action:			Date:	
Type: Bradenhead		# 1		
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 217876 Type: WELL API Number: 071-06655 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI  
Flowline valve closed at wellhead

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/14/2015 Annual Brhd Completed? \_\_\_\_\_

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Form 4 on file

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Optical Gas Imaging Survey**

Survey Type: Routine

Current Operations:  Production     Workover     Flowback     Referred to APCD

GPS(entrance of location): Lat: 37.102823    Long: -104.771114

Wind: Light    Speed: 5 (mph)    Direction From: NW    Weather: Clear    Temperature: 67 (F)

Assisting Staff: Tom Beardslee    Camera #: \_\_\_\_\_

Visible Smoke     Referred to CDPHE

Times Surveyed    Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:00	AM	11:01	AM	Wellhead(s)

Comment: Wellhead leaking, 24 hrs to fix leak  
See uploaded video #1

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p><u>ECMC Inspection Report Summary</u>  <u>On 3/4/26 at approximately 11:00 Hrs, I, Inspector Abe Serna, conducted an on-site inspection.</u>  <u>Location: Lorencito 4-10-34-66</u>  <u>Operator: Evergreen Natural Resources</u>  <u>API#: 05-071-06655</u>  <u>County: Las Animas</u>  <u>While there, I observed a SI well</u>  <u>During this inspection the following possible compliance issues were observed:</u>  <u>Leaking Wellhead</u>  <u>Action Date 3/4/26 See attached video #.1</u>  <u>Corrective Action Date: 3/5/26</u>  <u>Weather conditions: Sunny</u>  <u>A follow up on this site inspection needs to be conducted to ensure the</u>  <u>Compliance issues have been corrected to comply with ECMC rules.</u>  <u>This is a summary of inspection report.</u></p> <p><u>Any corrective actions from previous inspections that have not been addressed are still applicable</u></p>	sernaa	03/04/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698708446	Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7468231">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7468231</a>
698708447	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7468232">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7468232</a>