

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/23/2026

Submitted Date:

02/26/2026

Document Number:

713401261

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
398876 _____ Popejoy, Dusty _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 76950
Name of Operator: SCHUMACHER* JOHN
Address: _____
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 5 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Chaivre, Annie		annie.chaivre@state.co.us	
Roberts, James		j75rober@blm.gov	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Heil, John		john.heil@state.co.us	
Katz, Aaron		aaron.katz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232299	WELL	PA	05/01/1962	DA	103-40088	USA--COLO 06412 2-G	PA

General Comment:

This is a Field Inspection/audit of the scout card, related documents and the location.

No operator contact information in the CECMC database.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Livestock/Barbed wire		
Corrective Action:		Date:	

Venting:

Yes/No	YES		
Comment:	Observed plugged and abandoned well actively venting gas during inspection. Optical Gas Imaging (FLIR) confirmed continuous venting from the well. Please refer to FLIR camera videos		
Corrective Action:	Well is to be re-entered and replugged to assure that all sources of hydrocarbons are isolated appropriately and potential to emit is eliminated. Form 6 Notice of Intent should be filed by March 26, 2026. It is expected that work is completed and reported by August 26, 2026.	Date:	03/26/2026

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232299 Type: WELL API Number: 103-40088 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: P&A well actively venting gas at time of inspection.

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Complaint

Current Operations: Production Workover Flowback Referred to APCD

GPS(entrance of location): Lat: 40.087346 Long: 108.776706

Wind: Calm Speed: _____ (mph) Direction From: West Weather: Clear Temperature: 42 (F)

Assisting Staff: _____ Camera #: 1

Visible Smoke Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
11:40	AM	11:45	AM	

Comment: _____

Corrective Action: _____

Date:

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 02/23/2026 at approximately 11:35 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit for a complaint, #200442262 at SCHUMACHER* JOHN USA--COLO 06412 #2-G well at Location ID #398876 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations. Location is approximately 17 yards east of Highway 139 between mile marker 72 and Highway 64.</p> <p>While there, I observed plugged and abandoned well actively venting gas Optical Gas Imaging (FLIR) confirmed continuous venting from the well.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Venting - Plugged and abandoned well actively venting gas during inspection. Optical Gas Imaging (FLIR) confirmed continuous venting from the well with a CA date of 03/26/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	02/25/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404559081	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462120
713401262	713401261 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462116
713401263	713401261 Inspection-Audit FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462117
713401264	713401261 Inspection-Audit FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462118
713401265	713401261 Inspection-Audit FLIR video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7462119

