

Inspection Photos

API: 017-06389

Operator: MURFIN DRILLING COMPANY

Inspection Date: 3/3/2026

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the east side of the location. This area consist of undesirable weeds (Kochia).



Inspection Photos



Photo 2. Center of the location facing north.



Inspection Photos



Photo 3. Center of the location facing west. The west side of the location has desirable vegetation with minimal weeds.



Inspection Photos



Photo 4. Center of the location facing south. The left side of the line is dominantly undesirable weeds.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 5. Center of the location facing east. The east side of the location consists mostly of undesirable weeds (Kochia).



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-06389 | Date: 3/3/2026