

Inspection Photos

API: 017-06519

Operator: OGRIS OPERATING LLC

Inspection Date: 3/3/2026

County: CHEYENNE



Inspection Photos



Photo 1. Facing south toward the access road which has not been reclaimed. The gravel road base needs to be removed and soils need to be decompacted by cross ripping to 18 inches.



Inspection Photos



Photo 2. There is a metal pipe that remains along the access road that needs to be removed if associated with the wellsite.



Inspection Photos



Photo 3. End of the access road facing north. The access road needs to be decompacted and reclaimed back to cropland.



Inspection Photos



Photo 4. Facing east toward the location.



Inspection Photos



Photo 5. View of ground cover showing rocks at the location. Bigger rock will need to be picked up.



Inspection Photos



Photo 6. East side of the location facing west. There are areas of the location that don't show signs of crop growth.



Inspection Photos



Photo 7. Facing east toward the surrounding undisturbed crop. There are very few rocks observed outside of the location.

