

# Inspection Photos

API: 017-06378

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/3/2026

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west along the access road. Gravel remains along the road.



## Inspection Photos



**Photo 2.** Facing west further along the road. Soil has been placed on this portion of the road.



## Inspection Photos



**Photo 3.** Facing southwest at the location. It appears soil was placed on the location however the location was not recontoured and soils underneath the soil may not have been decompacted..



## Inspection Photos



**Photo 4.** Facing southeast at the location. There is a cut slope at the red arrow where soil needs to be recontoured back to the terrain.



## Inspection Photos



**Photo 5.** The powerline servicing the former wellsite needs to be removed



## Inspection Photos



**Photo 6.** Facing east at the south side of the location.



## Inspection Photos



**Photo 7.** The soils in the area shown in the previous photo has very compacted soils that a shovel could not penetrate. Soils also appear to be discolored in this area.

