

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2026

Submitted Date:

02/27/2026

Document Number:

715203979

FIELD INSPECTION FORM

Loc ID 304731 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273751	WELL	PR	02/01/2005	GW	125-08919	ROSE 31-18	PR

General Comment:

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

Location					
Lease Road:					
	Type	Access			
	comment:	Two track through pasture			
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
	Type	TANK LABELS/PLACARDS			
	Comment:	Metal sign by water tank			
Corrective Action:					Date:
	Type	WELLHEAD			
	Comment:	Lease sign by wellhead			
Corrective Action:					Date:
Emergency Contact Number:					
	Comment:	<input style="width: 100%;" type="text"/>			
Corrective Action:		<input style="width: 100%;" type="text"/>			Date: _____
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
	Comment:	<input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
	Type	WELLHEAD			
	Comment:	Metal panels around wellhead			
Corrective Action:					Date:
Equipment:					
					corrective date
Type:	Plunger Lift	#	1		
Comment:	Lubricator, motor valve and controller are installed				
Corrective Action:					Date:
Type:	Vertical Separator	#	1		
Comment:	Vertical gas separator in fiberglass shed				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.889310,-102.229550
Comment:	Fiberglass water tank 50% buried				
Corrective Action:					Date:
Paint					

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 273751 Type: WELL API Number: 125-08919 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central meter run for \(Odell 44-7, Shay 34-7, Rose 31-18, 41-18\) 1870' NE @ Odell 44-7](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment: [Access has erosion](#)

Corrective Action: [Repair erosion on access](#)

Date: 04/25/2026

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404561036	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7463885
715204008	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7463880