

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 329657

Inspection Document #: 720300106

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SEW

Location ID: 329657



Photo 1. Photo taken from access road showing bare spoil and some growth of desirable grass species.

Photo 2. Photo taken on the access road looking down on the location. Areas with bare soil and also large numbers of annual weeds are present on the south side of the access road and on the site. Bunch grass is present on the north side of the site and along the access road.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SEW

Location ID: 329657



Photo 3. Photo taken from access road showing drill seeding rows that have stunted vegetation growth.



Photo 4. Photo taken from the west edge of the location facing north. See comment under photo 3. The majority of vegetation growth is undesirable annual weeds.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SENW

Location ID: 329657

Feb 6, 2026 at 12:10:55 PM
+40.430846,-104.880790
352° N
Windsor CO 80550
United States



Feb 6, 2026 at 12:11:01 PM
+40.430846,-104.880790
63° NE
Windsor CO 80550
United States



Photo 5. Photo taken from location facing north showing a significant area covered by undesirable vegetation and areas with bare soil.

Photo 6. Photo taken from location facing east. See comment under photo 5.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SENW

Location ID: 329657



Photo 7. Photo taken from the location facing west. Some desirable grasses are present; however, there are also bare areas and undesirable vegetation.



Photo 8. Photo taken on location of bare soil between bunch grass that is conserving for stormwater erosion.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SEW

Location ID: 329657



Photo 9. Photo taken of access road facing up slope showing stunted vegetation, areas of bare soil and undesirable annual weeds.



Photo 10. The photo shows a clear line where the access road was present, and the area was disturbed, and the adjacent reference area that was not impacted.

