

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 330418

Inspection Document #: 720300109

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 1. Photo taken from center of location facing south, showing desirable forb and grass species establishment as well as some undesirable weeds on the location.



Photo 2. Photo taken from center of location facing west. See comment under photo 1.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 3. Photo taken from center of location facing east. See comment under photo 1.



Photo 4. Photo taken from center of location facing north. See comment under photo 1.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 5. Photo taken from location showing desirable vegetation growing on location.



Photo 6. Photo shows some weeds growing on location with drill seed rows showing evidence of reclamation activity. Growth of desirable vegetation on location.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 7. Photo shows desirable vegetation as well as some weeds present on well pad.

Photo 8. Photo taken on north west corner of location showing bare earth and evidence of drill seeing rows.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 9. Photo taken from western side of location facing north west. See comment under photo 8.



Photo 10. Photo taken from western side of location facing north. See comment under photo 8.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 11. Photo taken on western side of location undesirable vegetation and some patches bare soil. There is also growth of desirable grass species.

Photo 12. Photo taken from main access road northwest past location showing erosion on main road.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 13. Photo taken from main access road north west past location showing erosion on main road.



Photo 14. Photo taken from main access road north west past location showing erosion on main road.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418

Feb 6, 2026 at 1:18:01 PM
+40.425293,-104.880353
240° SW
Greeley CO 80634
United States

Feb 6, 2026 at 1:18:03 PM
+40.425297,-104.880347
316° NW
Greeley CO 80634
United States

Photo 15. Photo taken from the tank battery location showing drill-seeded rows of desirable grass species; also present are a large amount of bare area and some undesirable annual weed species.

Photo 16. Photo taken from tank battery location. See comment under photo 15.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 17. Photo taken from tank battery location. See comment under photo 15.

Photo 18. Photo taken from tank battery location. See comment under photo 15.

Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 19. Photo taken from the tank battery location. Showing Russian thistle and desirable grass species. Also, bare spoil present.



Photo 20. Photo taken from tank battery location. See comment under photo 15.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3SESW

Location ID: 330418



Photo 21. Photo taken from tank battery location. See comment under photo 15.

