

Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 464085

Inspection Document #: 720300123

Weld County, CO

Isaac Thibedeau
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: SHUR VIEW-65N67W-TANK/3SWNW

Location ID: 464085



Photo 1. Photo taken from the southeastern corner of the location. It appears that an attempt to revegetate the location was made based on evidence of drill seed rows; however, vegetation cover has not achieved 80% cover compared to a

Photo 2. Photo of desirable grass species present on location.



Inspection Photos
Location Name: SHUR
VIEW-65N67W-TANK/3SWNW
Location ID: 464085



Photo 3. Photo taken from location facing south showing a large amount of bare areas. The location needs to be vegetated to prevent erosion. Downslope west is sensitive riparian habitat.



Photo 4. Photo taken from location facing south west. see comment under photo 3

Inspection Photos

Location Name: SHUR VIEW-65N67W-TANK/3SWNW

Location ID: 464085



Photo 5. Photo taken from a location on the southern portion of the location facing southwest, showing a significant bare area.



Photo 6. Photo taken from a location in the southwestern portion of the site, facing south, showing bare earth and undesirable weeds.

Inspection Photos

Location Name: SHUR VIEW-65N67W-TANK/3SWNW

Location ID: 464085



Photo 7. Photo taken from the southwestern portion of location facing south east. Some desirable grasses are present however there are bare areas as well as undesirable weeds growing.

Photo 8. Photo taken on location facing northeast showing growth of desirable grasses however some undesirable weeds are also present.

Inspection Photos

Location Name: SHUR VIEW-65N67W-TANK/3SWNW

Location ID: 464085



Photo 9. Photo taken at the location where the flowline was removed, heading to location 330415. The area appears to have stalled for reclamation, and the bare area needs to be seeded.

Photo 10. Photo shows undesirable plant species present on flowline scare.