

# Final Reclamation Inspection

February 11, 2026

Operator: KIMBARK OIL & GAS COMPANY

Location ID: 395521

Inspection Document #: 720300115

Morgan County, CO

Isaac Thibedeau  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: MERINO STATE-66N55W 36SWSE

Location ID: 395521



**Photo 1.** Photo taken from south of the location where the historic access road was facing southeast. The area has evidence of stormwater erosion. Road appears to have been installed in a depression between two hills, making it susceptible to stormwater erosion. Vegetation present is native perennial.

**Photo 2.** Photo taken from location facing west showing where water accumulates and area of bare soil.

## Inspection Photos

Location Name: MERINO STATE-66N55W 36SWSE

Location ID: 395521



**Photo 3.** Photo taken from location facing south, showing some bare soil as well as native vegetation present on location.



**Photo 4.** Photo taken from the above location facing southeast. Showing growth of desirable grass and forb species. The area where water has accumulated can also be seen towards the top of the photo.

## Inspection Photos

Location Name: MERINO STATE-66N55W 36SWSE

Location ID: 395521



**Photo 5.** Photo taken from west of location at the top of the showing bare soil areas that are concerning for stormwater erosion.

**Photo 6.** Photo of the hill to the west of the location. See comment under photo 5.



Inspection Photos

Location Name:MERINO STATE-66N55W 36SWSE

Location ID: 395521



**Photo 7.** Photo taken from west of location. See comment in photo 5.



**Photo 8.** Photo taken from hill top west of location. See comment under photo 5.

## Inspection Photos

Location Name: MERINO STATE-66N55W 36SWSE

Location ID: 395521



**Photo 9.** Photo taken from west of the location on the hilltop. The cement pad from that well is still present and needs to be removed. Bare areas present around the pad need to be vegetated with desirable native grass and shrub species.



**Photo 10.** Photo taken from the hilltop west of the well. See comment under photo 9.