

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2026

Submitted Date:

03/06/2026

Document Number:

716302010

**FIELD INSPECTION FORM**

Loc ID 308990 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	<a href="#">All Inspections</a>
B WARD, GIENA		gward@ogrisop.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286228	WELL	PR	02/15/2008	CBM	071-08928	APACHE CANYON 18-16	PR

**General Comment:**

[CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.](#)

**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR. PHOTO 6: AREA OF IMPACTED SOIL FROM PRIME MOVER HYDRALIC HOSE.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.		Date: 03/12/2026

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:

Type: Other	# 1		
Comment:	PHOTO 9: Gauge hatch open when not being accessed for gauging or not sealed.		
Corrective Action:	Close and seal gauge hatches when not accessing tank per Rule 608.		Date: 03/07/2026
Type: Bird Protectors	# 1		
Comment:	PHOTO 9: Equipment does not properly prevent wildlife entrance or egress (BIRD PROTECTION).		
Corrective Action:	Install or repair wildlife protection equipment PER RULE 608.b.(7).		Date: 03/12/2026
Type: Compressor	# 1		
Comment:	PHOTO 7: Vacuum pump observed on well without ECMC approval.		
Corrective Action:	Provide ECMC with documentation showing approval of use of vacuum pump.		Date: 03/24/2026

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 286228 Type: WELL API Number: 071-08928 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 11/19/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: **PHOTO 9: OILY WASTE IN PRIME MOVER ENGIN SKID WITHOUT WILDLIFE PROTECTION SCREENS OR NETTING.**

Corrective Action: **DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 24 HOURS TO DRAIN OILY WASTE OR INSTALL WILDLIFE PROTECTION 3/12/2026 FOR ANY IMPACTED SOILS.**

Date: 03/12/2026

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 292586      Lat: 37.077040      Long: -104.921100

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Anchor Trench Present: NO      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	292586	2059099	
	292586	2059099	

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary                      Date: 3/5/2026                      Time: 19:57                      Operator: Ogris Operating LLC.10758                      Location: APACHE CANYON 18-16                      API# 05-071-08928                      County: Las Animas County.                      While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: IMPACTED SOIL, COMPLY WITH RULE 1002,.(2).D.CA DATE 3/12/2026. NO ECMC APPROVAL FOR VACUUM, CA DATE 3/24/2026. WILDLIFE PROTECTION, RULE 608.b.(7). CA DATE 3/12/2026. GUAGE HATCH OPEN ON PRODUCE WATER TANK, Rule608. CA DATE 3/7/2026. OILY WASTE IN ENGINE SKID, RULE 1002..(2).D &amp; 1002.f.(2)B, CA DATE 24 HOURS TO DRAIN OILY WASTE OR INSTALL WILDLIFE PROTECTION 3/12/2026 FOR ANY IMPACTED SOILS. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	03/06/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302016	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7471404">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7471404</a>