

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2026

Submitted Date:

03/06/2026

Document Number:

719001552

FIELD INSPECTION FORM

Loc ID: 326335 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216252	WELL	SI	12/01/2025	CBM	067-07858	GIGI SHAPIRO A 1	SI

General Comment:

Inspection Report Summary
On 3/6/26 I Inspector Charles Garcia conducted an on-site inspection.
Location: GIGI SHAPIRO A 1
Operator: Simcoe LLC
API#: 067-07858
County: LaPlata
All prior CA's still stand

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Contact # 970-247-6916 Emergency #911	
Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment:
 Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	TELEMETRY EQUIPMENT CATTLE PANELS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	2 TELEMETRY EQUIPMENT LUBE OIL CONTAINER FOR PRIME MOVER		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		

Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 216252 Type: WELL API Number: 067-07858 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/14/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
NO ISSUES FOUND	garciacr1	03/06/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001553	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7471527