

# QB ENERGY OPERATING LLC BENTLEY-67S95W 11SWSE Facility # 324168



**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SWSE  
Facility # 324168**



**500 gallon methanol tank paint is fading and showing signs of rust.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SWSE  
Facility # 324168**



**East tank has seep occuring near the bottom of tank.**




**East tank has seep occuring near the bottom of tank.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SWSE  
Facility # 324168**




**West tank is rusted out neat the bottom of tank. West tank is shut in and is empty.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SWSE  
Facility # 324168**



**West tank is rusted out neat the bottom of tank. West tank is shut in and is empty.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SWSE  
Facility # 324168**



**West tank in rusted out neat the bottom of tank. West tank is shut in and is empty.**