

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766




Photo # 7268 From entrance to location

Photo # 7229 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7270 Location



Photo # 7271 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7272 Location



Photo # 7273 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7274 Location



Photo # 7275 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7276 Leak/bubbling around CHEVRON 44-5D wellhead



Photo # 7277 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7278 Leak/bubbling around CHEVRON 44-5D wellhead



Photo # 7279 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7280 Leak/bubbling around CHEVRON 44-5D wellhead



Photo # 7281 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7282 Leak/bubbling around CHEVRON 44-5D wellhead



Photo # 7283 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7284 Leak/bubbling around CHEVRON 44-5D wellhead



Photo # 7285 Leak/bubbling around CHEVRON 44-5D wellhead

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766



Photo # 7286 External corrosion visible on separator & staining near separator



Photo # 7287 External corrosion visible on separator & staining near separator

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON-66S96W 4SWSW (PARACHUTE CREEK 8)

Location #: 335766




Photo # 7288 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife