

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2026

Submitted Date:

03/01/2026

Document Number:

711902913

FIELD INSPECTION FORM

Loc ID: 312299 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason	(303) 330 - 1921	jharms@strachanexploration.com	
Binschus, Chris		chris.binschus@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221131	WELL	PR	06/01/2023	OW	075-09257	BANEY-STATE 16-3	PR

General Comment:

THIS IS AN AUDIT OF THE WELL FILE, SCOUT CARD AND RELATED DOCUMENTS.
LAST FIR 9-2-2025
THIS WELL IS PR, THE RELATED BATTERY IS ATTACHED TO THIS FIR FOR CA'S
STORMWATER EROSION CA CITED WITHIN THIS FIR - CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES #8) HRS.
REPAIR/INSTALL BMP'S SEE PHOTOGRAPHS ATTACHED

Location

Lease Road:

Type	Access		
comment:	STORMWATER EROSION MANAGEMENT - LEASE ROAD TO TANK BATTERY CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES - (48) HRS. TO REPAIR/INSTALL BMP'S SEE PHOTOGRAPHS ATTACHED		
Corrective Action:	INSTALL OR REPAIR REQUIRED BMP'S PER RULE 1002 SERIES	Date:	03/03/2026

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	SATISFACTORY		
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	STORMWATER EROSION ON LEASE ROAD TO BATTERY SEE ATTACHED PHOTOGRAPHS AND COMPLY WITH RULE 1002 SERIES. CONTACT ECMC RECLAMATION GROUP FOR DIRECTIVES - (48) HRS. TO REPAIR		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: NONE OBSERVED

Multiple Spills and Releases?

Equipment:

Type: Other	# 0				corrective date
Comment:	NO CHANGE IN EQUIPMENT INVENTORIED				
Corrective Action:		Date:			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	NO CHANGE IN TANK CONFIGURATION				
Corrective Action:		Date:			

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 221131 Type: WELL API Number: 075-09257 Status: PR Insp. Status: PR

Producing Well

Comment: OW

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ROUTINE FIR - CA'S CITED WITHIN THIS DOCUMENT	schureky	03/01/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404561758	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464669
711902917	PHOTOGRAPHS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7464668