

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2026

Submitted Date:

03/02/2026

Document Number:

719001479

**FIELD INSPECTION FORM**

Loc ID: 333079  
Inspector Name: GARCIA, CHARLES  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 600 17TH STREET STE 1400S  
City: DENVER State: CO Zip: 80202

**Findings:**

- 15 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		Inspections@catamountep.com	SJB inspections
McDonough, Corey		corey.mcdonough@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205173	WELL	PR	01/12/2024	GW	007-06049	ARGENTA FEE 18	PR
205217	WELL	PR	04/01/2020	CBM	007-06094	Argenta Fee 19	PR

**General Comment:**

Inspection Report Summary  
On 2/26/26 | Inspector Charles Garcia conducted an on-site inspection.  
Location: ARGENTA FEE 19, ARGENTA FEE 18  
API# 067-06049  
API# 067-06094  
Operator: CATAMOUNT ENERGY PARTNERS LLC  
County: LaPlata  
All prior CA's still stand.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	LOCATION SIGNS ARGENTA FEE 18 SHOWS BIG RUN PRODUCTION NOT CATAMOUNT		
Corrective Action:	Install sign or correct sign per rule 605		Date: 03/09/2026
Emergency Contact Number:			
Comment:	903-521-2990 911 EMERGENCY		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Land owner has Equipment on location. SEE LOCATION PICTURES		
Corrective Action:	Equipment not necessary for oil and gas operations.Store equipment off pad/interim reclamation area or obtain variance per rule 606.a(2),		Date: 03/02/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	HOG WIRE		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	METER HOUSES TELEMETRY EQUIPMENT HOG WIRE		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 2	corrective date	
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	GAS		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	At Argenta 18 well, pump jack and prime mover appear unused and non-serviceable. Remove all unused and non-serviceable equipment or maintain and return to service		
Corrective Action:	Remove all unused and non-serviceable equipment or maintain and return to service per 1000 series rules		Date: 05/01/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 205173 Type: WELL API Number: 007-06049 Status: PR Insp. Status: PR

**Producing Well**

Comment: SHARED LOCATION WITH ARGENTA FEE 18

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 205217 Type: WELL API Number: 007-06094 Status: PR Insp. Status: PR

**Producing Well**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404563329	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465904</a>
719001480	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465895">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7465895</a>