

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 5933 From entrance to location




Photo # 5934 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 5935 Location



Photo # 5936 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 5937 Location

Photo # 5938 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3598 From inspection/audit 708908346 conducted on 01/21/2026 - Open ended load line

Photo # 5939 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 3599 From inspection/audit 708908346 conducted on 01/21/2026 - Open ended load line

Photo # 5940 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT GM 41-29 Pad

Location ID: 335075



Photo # 5941 Debris



Photo # 5942 Debris