

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2026

Submitted Date:

03/03/2026

Document Number:

721100190

**FIELD INSPECTION FORM**

Loc ID 313581 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10506  
Name of Operator: SEELEY OIL COMPANY LLC  
Address: PO BOX 1058  
City: CORTEZ State: CO Zip: 81321

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Seeley, Nathaniel	(970) 565-2136	nathaniel@seeleyoil.com	<a href="#">All SW field inspections</a>
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263911	WELL	SI	10/01/2025	OW	083-06595	CUTTROAT 14	SI

**General Comment:**

On Monday, March 02, 2026, at 4:45 PM, southwest compliance inspector Jamie Blair performed an inspection on Cutthroat 14 well. There was no bird protector on the separator exhaust stack.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Road is native surface, rutted.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Location sign at pad entrance.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	24 hour contact: 970-565-2136. Emergency = 911.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	2-2" flowlines from wellhead to separator. 2-2" flowlines from separator to oil/produced water tank. 1-1" flowline from wellhead to pump jack engine fuel gas. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite Nat. gas.gathering system. 1-2" flowline for oil gathering.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	wellhead		

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	Horizontal heated separator is missing bird protector on vent stack. Photo 6.		
Corrective Action:	Install or repair bird protector to comply with 608.b.(7)	Date:	03/09/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER		OTHER	PBV FIBERGLASS		37.416571,-108.914042
Comment:	Tank is in unlined earthen berm.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	produced water and oil
Other (Capacity)	79 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 263911 Type: WELL API Number: 083-06595 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/28/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Native surface road and pad. Rutted. Muddy when wet.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Install bird protector</a>	blairj1	03/02/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404564643	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467077">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467077</a>
721100191	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467045">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7467045</a>