

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2026

Submitted Date:

03/10/2026

Document Number:

717300810

FIELD INSPECTION FORM

Loc ID 327382 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246801	WELL	PA	11/13/2025	GW	123-14598	WALSH GAS UNIT 6-24	PA
327382	LOCATION	AC	12/08/2025		-	WALSH GAS UNIT-62N68W 24NWSE	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 246801 Type: WELL API Number: 123-14598 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 327382 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404565682 received on 03/06/2026: While conducting facility decommissioning activities at the Walsh GU 6-24, U 24-15JI Facility, historically impacted soil was discovered at the aboveground storage tank (AST). The volume of the release is unknown. Assessment activities are ongoing. The facility is being permanently removed.	maclarej	03/10/2026
As outlined on ECMC form 19 spill report Doc #404565587 received on 03/06/2026: While conducting wellhead and flowline removal activities at the Walsh Gas Unit 6-24 Wellhead, historically impacted soil was discovered at the separator riser. The volume of the release is unknown. Assessment activities are ongoing. The wellhead and flowline are being permanently removed.	maclarej	03/10/2026
Well is plugged and abandoned (Walsh GU 6-24); ECMC form 42 notice of start of plugging operations doc #404456433 received on 11/13/2025. The facility/ tank battery has been decommissioned; tanks and equipment removed. ECMC form 42 notice of flowline abandonment completed doc #404439750 received on 11/18/2025. Bellhole excavations observed at flowline pipe removal pull points between WH & battery (backfilled). No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	03/10/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300814	Excavation at facility/ battery; No FL's/ risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474284
717300815	PA well; FL removed/ BH's backfilled	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474285