

# Inspection Photos

03/05/2026

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335044

**Inspection Doc:** 719200916

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 3:** Photos showing an example of newer wellhead signs with missing API numbers; comply with Rule 605.d.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 4:** Photos showing stained soils around wellhead RU 43-6; clean up/removal of stained soils pursuant to Rule 912.a. is required. Wellhead sign is missing API number.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 5:** Photos showing an example of erosion and rilling that is occurring on the northern corner of the location and discharging into the interim area; stormwater BMP's appear to be missing or insufficient. Maintenance is required; comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 6:** Photos showing examples of rips/tears in the corners of the secondary containment's black geotextile liner. Comply with Rule 603.o.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335044



**Photo 7:** Photos showing an overview of the northwestern and southern interim areas; interim areas are well established with big sagebrush. Interim areas appear to be progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources