

**Comment:** Stained soil beneath wellhead. Photo 2.

**Corrective Action:** Remove stained soil to comply with 1002.f.(2).D **Date:** 03/11/2026

Stained soil has been cleaned up.

**Comment:** Rod oiler over lubricating and staining soil beneath.

**Corrective Action:** Conduct maintenance on equipment, cleanup stained material and review self inspection processes to comply with 1002.f.(2).D. **Date:** 03/11/2026

Stained material has been cleaned up and maintenance has been completed.

**Comment:** Gas. Broken electrical conduit with exposed frayed wires. Photo 6.

**Corrective Action:** Install or repair wires to comply with 608.d. **Date:** 03/11/2026

Wiring has been repaired and oily jug has been removed.



