

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2026

Submitted Date:

03/11/2026

Document Number:

719001584

FIELD INSPECTION FORM

Loc ID: 325958 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	
, COGCC		michael.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215633	WELL	PR	01/10/1993	CBM	067-07238	SMITH FEDERAL 1	PR

General Comment:

Inspection Report Summary
On 2/11/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: SMITH FEDERAL 1
Operator: Simcoe LLC
API#: 067-07238
County: LaPlata
All prior CA's still stand.
GATE CAMBO 2802

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:			Date:

Emergency Contact Number:

Comment: Contact # 970-247-6916
Emergency #911

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Produced Water	Flow Line	>= 5 bbls	
Comment:	FLOW LINE LEAK GAS AND PRODUCED WATER OUTSIDE SEPARATOR BUILDING POSSIBLE GRADE 1 SEE LOCATION PICTURES AND VIDEO SIMCO WAS CONTACTED IMMEDIATELY UPON DISCOVERY		
Corrective Action:	CONTROL SPILL AND CLEAN UP FREE FLUIDS WITHIN 24 HRS SUBMIT FORM 19 WITHIN 24 HRS AND CONTACT JASON KOSOLA EPS WITHIN 72 HOURS PER RULE 906		Date: <u>03/12/2026</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	METER HOUSE TELEMETRY EQUIPMENT CATTLE PANELS		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:			Date:

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Other	# 1		

Comment:	WELLHEAD		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	FLOW LINE LEAK GAS AND PRODUCED WATER OUTSIDE SEPARATOR BUILDING POSSIBLE GRADE 1 SEE LOCATION PICTURES AND VIDEO SIMCO WAS CONTACTED IMMEDIATELY UPON DISCOVERY		
Corrective Action:	FIX AND TEST INTEGRITY OF FLOW LINE BEFORE RETURNING TO SERVICE		Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215633 Type: WELL API Number: 067-07238 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
FLOW LINE LEAK GAS AND PRODUCED WATER OUTSIDE SEPARATOR BUILDING POSSIBLE GRADE 1 SEE LOCATION PICTURES AND VIDEO SIMCO WAS CONTACTED IMMEDIATELY UPON DISCOVERY	garciacr1	03/11/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001585	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7476270
719001586	LOCATION VIDEO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7476271