

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404575879

Date Received:
03/11/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:
5 of 5 CAs from the FIR responded to on this Form
5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
BACA, DAVE	719-859-4066	dbaca@ogrisop.com
ZECHES, GIENA	7192204041	gzeches@ogrisop.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 716302010
Inspection Date: 03/05/2026 FIR Submit Date: 03/06/2026 FIR Status:

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC Company Number: 10758
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 308990

Location Name: APACHE CANYON-634S67W Number: 18SESE County: LAS ANIMAS
Qtrqtr: SESE Sec: 18 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.077050 Longitude: -104.921021

FACILITY - API Number: 05-071- -00 Facility ID: 286228

Facility Name: APACHE CANYON Number: 18-16
Qtrqtr: SESE Sec: 18 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.077050 Longitude: -104.921021

CORRECTIVE ACTIONS:

1 CA# 211412

Corrective Action: Close and seal gauge hatches when not accessing tank per Rule 608. Date: 03/07/2026

Response: CA COMPLETED Date of Completion: 03/11/2026

Operator Comment: THE TANK HATCH HAS BEEN CLOSED.

ECMC Decision:

ECMC
Representative:

2 CA# 211413

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D.

Date: 03/12/2026

Response: CA COMPLETED

Date of Completion: 03/11/2026

Operator Comment: ALL SOIL STAINS HAVE BEEN REMOVED FROM LOCATION AND ALL OPERATING EQUIPMENT HAS RECIEVED MECHANICAL MAINTENANCE.

ECMC Decision: _____

ECMC
Representative:

3 CA# 211414

Corrective Action: Install or repair wildlife protection equipment PER RULE 608.b.(7).

Date: 03/12/2026

Response: CA COMPLETED

Date of Completion: 03/11/2026

Operator Comment: THE OPEN VALVE HAS BEEN CAPPED.

ECMC Decision: _____

ECMC
Representative:

4 CA# 211415

Corrective Action: Provide ECMC with documentation showing approval of use of vacuum pump.

Date: 03/24/2026

Response: CA COMPLETED

Date of Completion: 03/11/2026

Operator Comment: FORM 4 DOC #404575833 FOR VACUUM PERMIT APPROVAL.

ECMC Decision: _____

ECMC
Representative:

5 CA# 211416

Corrective Action: DRAIN OILY WASTE REPAIR ALL LEAKS AND REMOVE IMPACTED SOIL PER RULE 1002..(2).D & 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 24 HOURS TO DRAIN OILY WASTE OR INSTALL WILDLIFE PROTECTION 3/12/2026 FOR ANY IMPACTED SOILS.

Date: 03/12/2026

Response: CA COMPLETED

Date of Completion: 03/11/2026

Operator Comment: THE UNUSED ENGINE AND SKID HAS BEEN REMOVED FROM LOCATION.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED, SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: _____

Title: ENVIRONMENTAL

Date: 3/11/2026 2:02:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404575899	PHOTO LOG
-----------	-----------

Total Attach: 1 Files