



PHOTO 1: ALL SOIL STAINS HAVE BEEN REMOVED FROM LOCATION AND ALL OPERATING EQUIPMENT HAS RECEIVED MECHANICAL MATINTENANCE. THE UNUSED ENGINE AND SKID HAVE BEEN REMOVED FROM LOCATION. A CAP HAS BEEN PLACED ON THE OPEN VALVE TO PREVENT WILDLIFE ENTRANCE.



PHOTO 2: THE TANK HATCH HAS BEEN SECURELY CLOSED. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.