

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2026

Submitted Date:

03/05/2026

Document Number:

717100483

FIELD INSPECTION FORM

Loc ID: 493349 Inspector Name: Rollins, Grace On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|------------------------------|
| , | | ECMCInspections@Oxy.com | All Inspections |
| Mickelson, Erik | | Erik_Mickelson@oxy.com | Oxy Environmental |
| Graber, Nikki | | nikki.graber@state.co.us | |
| Anderson, Laurel | | laurel.anderson@state.co.us | |
| Kiel, Macy | 970-515-1110 | Macy_Kiel@oxy.com | Staff Environmental Engineer |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|--|-------------|
| 493349 | LOCATION | AC | | | - | Cannon & UPRC 33-11&12J5 Location 493349 | EI |
| 493350 | TANK BATTERY | AC | 03/04/2026 | | - | Cannon & UPRC 33-11&12J5 TB 493350 | EI |

General Comment:

ECMC Field Inspection Report Summary
This is an environmental inspection. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Site Name: Cannon & UPRC 33-11&12J5 Tank Battery
Location ID: 493349
Facility ID: 493350
Date of Inspection: 03/03/2026
Weather: Mostly cloudy, wind ~16mph, 48°F

Note: Spill 493289 was reported on location at the meter house owned by another Operator and will be addressed under Field Inspection Report Document # 717100484.

- Current site status:
- Produced water vessel signage and placard are visible. Production tank labels are legible; placards are fading.
 - Signage with emergency contact number is illegible.
 - Staining is visible on the sides of the partially buried produced water vessel.
 - Debris is visible around the metal wire fence at the production tank and produced water vessel containment.
 - Rodent burrows are visible in the separator containment berm.

See attached corrective actions.

Location

Overall Good:

Signs/Marker:

| | | |
|--|--------------------|---|
| | Type | TANK LABELS/PLACARDS |
| | Comment: | Produced water vessel signage and placard are visible. Production tank labels are legible; placards are fading. |
| | Corrective Action: | Install or repair placard to comply with Rule 605.h.(3). Date: 05/05/2026 |

Emergency Contact Number:

Comment: Signage with emergency contact number is illegible.

Corrective Action: Install or repair sign to comply with Rule 605.h.(4). Date: 04/04/2026

Good Housekeeping:

| | | |
|------|--------------------|---|
| Type | DEBRIS | |
| | Comment: | Debris is visible around the metal wire fence at the production tank and produced water vessel containment. |
| | Corrective Action: | Remove debris to comply with Rule 606. Date: 03/12/2026 |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment: Spill 493289 was reported on location at the meter house owned by another Operator and will be addressed under Field Inspection Report Document # 717100484.

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: Rodent burrows are visible in the separator containment berm. | | | | |
| Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. Date: 04/04/2026 | | | | |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 493349 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 493350 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 404567960 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469702 |
| 717100487 | ECMC Photo Log - Cannon & UPRC 33-11&12J5 Tank Battery - 03.03.2026 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469701 |