

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2026

Submitted Date:

03/05/2026

Document Number:

718300124

FIELD INSPECTION FORM

Loc ID 307039 Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 52530
Name of Operator: MAGPIE OPERATING INC
Address: 2707 SOUTH COUNTY RD 11
City: LOVELAND State: CO Zip: 80537

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Carlile, Craig		craig.carlile@state.co.us	
Rollins, Grace		grace.rollins@state.co.us	
Warner, Ryan	720-233-0875	magpieoil@yahoo.com	All Inspections
Kost, Jody		magpieoil2@yahoo.com	
Allison, Rick		rick.allison@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216642	WELL	TA	03/18/2021	OW	069-05037	ANDERSON, J A 1	TA
307039	LOCATION	AC			-	ANDERSON, J A-65N68W 32SWSW	EI

General Comment:

On February 25th, 2026, ECMC Environmental Protection Specialists Grace Rollins and Laurel Anderson performed a routine environmental inspection at Magpie Operating Inc's (Operator) Anderson J, A 1 Well (API 069-05037) and Tank Battery on the ANDERSON, J A-65N68W32SWSW Location (Location ID 307039). Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

The Anderson J, A 1 Well (API 069-05037) and Tank Battery on the ANDERSON, J A-65N68W32SWSW Location (Location ID 307039) are surrounded by cropland and located within ¼ mile of:

- 1 or more occupied structures (residences)
- Surface water and a riverine wetland
- multiple roads and right-of-ways (State Highway 60 and multiple local roads)

Current site status:

- Stained soil was observed at the 300-bbl steel crude oil AST loadout located within the earthen secondary containment berm.
 - Grass/weeds were observed within one or more of the earthen secondary containment berms
 - Partially buried debris was observed on location
- See attached corrective actions.

Location

Overall Good:

Emergency Contact Number:

Comment: Emergency contact number present.

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Grass/weeds were observed within one or more of the earthen secondary containment berms and partially buried debris was observed on location.

Corrective Action: Comply with Rule 606.

Date: 03/18/2026

Overall Good:

Spills:

Type	Area	Volume		
Crude Oil	Truck Loadout			
Comment: Stained soil was observed at the 300-bbl steel crude oil AST loadout located within the earthen secondary containment berm.				
Corrective Action: Comply with ECMC Rules. Operator shall immediately control and contain spills/releases and investigate, clean up and document impacts per Rule 912.a.				Date: <u>03/05/2026</u>
Note: for any spills that do not meet the reporting requirements of Rule 912.b.; Operator shall provide documentation of the cleanup efforts (photo documentation and waste disposal manifests) to the Director per Rule 912.a.(5) - Operator may submit documentation via FIRR.				
Additionally, Operator shall properly handle, transport and dispose of E&P waste in accordance with 905 Series Rules.				

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216642 Type: WELL API Number: 069-05037 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 307039 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
PPE: Level D + FR Clothing Weather: Partly cloudy, 15 mph wind with higher gusts, 60°F	andersoln	03/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404568535	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7470117
718300125	2026_0225_Anderson J A 1 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7470101