

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2026

Submitted Date:

03/04/2026

Document Number:

720800330

**FIELD INSPECTION FORM**

Loc ID 424216 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10670  
Name of Operator: BISON IV OPERATING LLC  
Address: 518 17TH STREET SUITE 1800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff		jschneider@bisonog.com	<a href="#">All Inspections</a>
Garza, Tarah	970-514-3581	tgarza@bisonog.com	<a href="#">Environmental Compliance Specialist</a>
Buck, Paul	303-882-5868	pbuck@bisonog.com	<a href="#">ALL INSPECTIONS</a>
Milne, Rachel	720-370-8580	rmilne@bisonog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424216	LOCATION	AC	06/20/2025		-	Rothe 12-14-8-61	AC

**General Comment:**

This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location of a previously Plugged and Abandoned Well

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type STORAGE OF SUPL

Comment: Buildings from the Heater Treater and Gas Engine STILL appear to be on Location after Well was Plugged and Abandoned on 06.13.2025. 3 months to removed ALL surface equipment has past. See photos

Corrective Action: **Comply with Rule 1004**

Date: 03/27/2026

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 424216 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well appears to have been Plugged and Abandoned per Form 6S - 404254790 dated 07.11.2025.  
 All Surface Equipment has been removed except 2 Buildings. 3 Months to remove all Equipment has past.  
 Form 27S - 404562581 was filed on 03.02.2026 with updated to Soil Sampling.  
 Final Reclamation appears to be on going.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404567412	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469313">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469313</a>
720800331	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469293">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7469293</a>