

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2026

Submitted Date:

03/06/2026

Document Number:

701104559

FIELD INSPECTION FORM

Loc ID 334789 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211547	WELL	PR	05/01/2001	GW	045-07307	SHAEFFER 18-6	EG
259763	WELL	PR	09/20/2001	GW	045-07781	SHAEFFER 18-6B (F18)	EG
259764	WELL	PR	09/20/2001	GW	045-07782	SHAEFFER 18-6A	EG
259765	WELL	PR	08/24/2001	GW	045-07783	SHAEFFER 18-3A (F18)	EG
259773	WELL	PR	08/24/2001	GW	045-07784	SHAEFFER 18-3B (F18)	EG

General Comment:

[Flowline Integrity Inspection and Tank Integrity Inspection](#)
Patch on the south tank appears inadequately sealed.
Inspect the patch seal to determine if repair is need.
CA Date 3/22/2026
1000 gallon methanol tank paint is fading and showing signs of rust.

Location

Lease Road:

Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:	1000 gallon methanol tank paint is fading and showing signs of rust.				
Corrective Action:					Date:

Paint

Condition	Inadequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	STEEL AST			
Comment:				The south tank has a patch on top of it that looks not to be sealed fully.		
Corrective Action:				Date:	03/22/2026	

Paint	
Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:		
Yes/No		
Comment:		
Corrective Action:	Date:	

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 211547 Type: WELL API Number: 045-07307 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259763 Type: WELL API Number: 045-07781 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259764 Type: WELL API Number: 045-07782 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259765 Type: WELL API Number: 045-07783 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 259773 Type: WELL API Number: 045-07784 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404569723	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7471109
701104560	Flowline integrity inspection 701104559 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7471101