

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2026

Submitted Date:

03/13/2026

Document Number:

717300820

FIELD INSPECTION FORM

Loc ID: 329563 Inspector Name: Maclaren, Joe On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-

Findings:

4 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| | | ECMCInspections@Oxy.com | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|-----------|-------------------------------------|-------------|
| 249726 | WELL | TA | 05/27/2025 | GW | 123-17529 | HSR-COADY 12-28 | PA |
| 487932 | LOCATION | AC | | | - | HSR-COADY READY 28-3N-67WSWSW TBLoc | EG |

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
 Photos uploaded

Inspected Facilities

Facility ID: 249726 Type: WELL API Number: 123-17529 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487932 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

| Comment | User | Date |
|--|----------|------------|
| Well is plugged and abandoned (HSR Coady 12-28); ECMC form 42 notice of start of plugging operations doc #404384322 received 10/08/2025. Off location flowline AIP in progress; flowline risers at PA well is bullplugged/ valved OOSLAT. Flowline risers are labeled as flushed. Flowline at facility (inlet to HHS) is disconnected/ isolated and OOSLAT. Remediation work (PA well) is in progress. | maclarej | 03/13/2026 |
| As outlined on ECMC form 19 spill report Doc #404568257 received on 03/06/2026: While conducting wellhead plugging and abandonment and flowline removal activities at the HSR-Coady 12-28A wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. Assessment activities are ongoing. The wellhead has been plugged and abandoned. | maclarej | 03/13/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 717300826 | PA well & signage; FL riser OOSLAT/ flushed | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7480144 |
| 717300827 | FL's at HHS disconnected/ isolated & OOSLAT | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7480145 |