

Inspection Photos

Location Name: Dillard USX/AB29-02

Location #: 420817



Photo #1

Dillard USX AB29-02 (123-32720) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-surface



Photo #2

Dillard USX AB29-02 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Cement-surface
Site safety signage



Inspection Photos

Location Name: Dillard USX/AB29-02

Location #: 420817



Colorado Energy & Carbon Management Commission
Weld County
+40.549483 -104.570665
5° N
2026-03-10 12:46

Photo #3

Dillard USX AB29-02 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface

wellsite signage



Colorado Energy & Carbon Management Commission
Weld County
+40.544705 -104.564562
323° NW
2026-03-10 12:39

Photo #4

Dillard USX AB29-02 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface

Wellsite entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Dillard USX/AB29-02

Location #: 420817




Photo #5

Dillard USX AB29-02 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface

JSA; 2026-03-10;

Digital on file



Photo #6

Dillard USX AB29-02 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: Cement-surface

Well; Operator photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources