

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2026

Submitted Date:

03/16/2026

Document Number:

708908717

FIELD INSPECTION FORM

Loc ID 335585 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 30 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280441	WELL	SI	11/01/2025	GW	045-11254	CHEVRON 5-333D	PR
280442	WELL	PR	04/01/2025	GW	045-11255	CHEVRON 5-432D	PR
280443	WELL	SI	05/01/2025	GW	045-11256	CHEVRON 5-433D	SI
280444	WELL	PR	08/01/2012	GW	045-11257	CHEVRON 5-332D	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
	Type CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type OTHER		
Comment:	Sign at entrance to location		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:	Partially buried tank lacks capacity (additionally tank labels have previous operator name) Please refer to FIR document # 701104578 for CA		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
	Type WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Sandpiper pump		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Marked		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,

Comment:	Partially buried tank - tank appears to be double walled	
	Tank not equipped with telemetry	
Corrective Action:		Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	Unknown - tank lacks capacity
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:	Tanks not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment:	Centralized containment			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 280441 Type: WELL API Number: 045-11254 Status: SI Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420 Additionally the CHEVRON 5-432D, CHEVRON 5-433D & CHEVRON 5-332D wells also lack wellbore diagrams/not in compliance with CECMC Rule 420	
Corrective Action:	Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17	Date: <u>04/15/2026</u>

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280442 Type: WELL API Number: 045-11255 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280443 Type: WELL API Number: 045-11256 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:	Shut In - Last produced April 2025 Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 280444 Type: WELL API Number: 045-11257 Status: PR Insp. Status: PR

Producing Well

Comment:	Producing, well on plunger lift Well lacks wellbore diagram/not in compliance with CECMC Rule 420 - Comply with CECMC Rule 420 & submit wellbore diagram via FORM 4 SUNDRY or FORM 17	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Gravel						Sparse to none in areas
		Berms				
Berms						
		Rip Rap				
				Material Handling And Spill Prevention		Chemical tank containment
		Check Dams				
		Gravel				Sparse to none in most sections
Compaction						Light compaction in some areas
		Compaction				Light comapction in some sections
		Ditches				

Comment: Chemical tank containment approximately 3/8 full of fluid/may need maintenance in the near future

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 03/11/2026 at approximately 10:08 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC CHEVRON M04 696 Pad Location # 335585 in Garfield County Colorado. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 111 yards from Parachute Creek. While there, I observed normal production operations.</p> <p>During this inspection/audit the following compliance issues were observed:</p> <p>1. Inspected Facilities - CHEVRON 5-333D, CHEVRON 5-432D, CHEVRON 5-433D & CHEVRON 5-332D wells lack wellbore diagrams - Comply with Rule 420 with a CA date of 04/15/2026</p> <p>Comments -</p> <p>Signs/Marker - Partially buried tank lacks capacity & tank labels have previous operator name - Please refer to FIR document # 701104578 for CA</p> <p>Stormwater - Chemical tank containment approximately 3/8 full of fluid/may need maintenance in the near future</p> <p>A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection/audit report.</p> <p>Any corrective actions from previous inspections/audits that have not been addressed are still applicable.</p>	smelserw	03/16/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708908718	Inspection/Audit 708908717 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482688
708908719	Inspection/Audit 708908717 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7482689