

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: 03/05/2026 Submitted Date: 03/10/2026 Document Number: 707801893
FIELD INSPECTION FORM			

Loc ID 436642	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
------------------	----------------------------------	---	-------------------	--

Operator Information:

ECMC Operator Number: 10805

Name of Operator: FULCRUM ENERGY OPERATING LLC

Address: 240 SAINT PAUL STREET SUITE 502

City: DENVER State: CO Zip: 80206

Findings:

9 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Fulcrum		inspections@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489246	WELL	AP	02/10/2025		057-06647	Lupine 0880 1-32D SWD	AP

General Comment:

ECMC Inspection Report Summary

On Thursday 3/5/2026, I, Inspector Scott Ramsey, conducted a routine inspection/audit at Ray Ranch CTB, at Location # 436642 in Jackson County Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

During this inspection the following possible compliance issues were observed:

1. Some debris.
2. No evidence of meter calibration cards.
3. Totes not in containments and chemicals spilled all around risers.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	some chemical tanks/ totes are labeled properly		
Corrective Action:	Provided proper labeling	Date:	03/20/2026
Emergency Contact Number:			
Comment:	911/970-594-0477		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	1. Some debris.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Totes not in containments and chemicals spilled all around risers.		
Corrective Action:	Provide proper secondary containments for chemical totes. Operators will design secondary containment structures to be sufficiently sized to contain at least 150% of the volume of the largest single Tank within the containment. Operators will construct secondary containment of steel, or other engineered material, designed and installed to prevent leakage and resist degradation from erosion or routine operation.		Date: 03/20/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Ancillary equipment	# 11	corrective date	
Comment:	500 gallon tanks in metal containments		
Corrective Action:			Date:
Type: Ancillary equipment	# 7		
Comment:	Natural gas generators for crypto mining		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemicale totes not in containments see housekeeping for C/A		
Corrective Action:			Date:
Type: Ancillary equipment	# 14		
Comment:	Crypto mining equipment		
Corrective Action:			Date:
Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 489246 Type: WELL API Number: 057-06647 Status: AP Insp. Status: AP

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404574527	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475246
707801898	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475225