

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2026

Submitted Date:

03/10/2026

Document Number:

719001577

**FIELD INSPECTION FORM**

Loc ID 333591 Inspector Name: GARCIA, CHARLES On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10749  
Name of Operator: SIMCOE LLC  
Address: 1199 MAIN AVE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
		ehsinspections@machnr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215623	WELL	PR	11/01/2018	CBM	067-07228	KNIGHT E 1	PR

**General Comment:**

Inspection Report Summary  
On 3/10/26 | Inspector Charles Garcia conducted an on-site inspection.  
Location: KNIGHT E1  
Operator: Simcoe LLC  
API#: 067-07228  
County: LaPlata  
All prior CA's still stand

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK HAS NO PLACARD SEE LOCATION PICTURES		
Corrective Action:	Replace/install labels/placards per Rule 605	Date:	03/13/2026
Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK TELEMETRY EQUIPMENT METER HOUSE CATTLE PANELS		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Other # 1			corrective date
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Other # 1			
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Vertical Heated Separator # 1			
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment:	95 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 215623 Type: WELL API Number: 067-07228 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/21/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">PRODUCED WATER TANK HAS NO PLACARD SEE LOCATION PICTURES</a>	garciacr1	03/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404574536	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475268">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475268</a>
719001579	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475242</a>