

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2026

Submitted Date:

03/10/2026

Document Number:

719500948

**FIELD INSPECTION FORM**

Loc ID: 312723    Inspector Name: Morris, Matthew    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

ECMC Operator Number: 10844

Name of Operator: QB ENERGY OPERATING LLC

Address: 1001 17TH STREET SUITE 1600

City: DENVER    State: CO    Zip: 80202

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283915	WELL	PR	12/01/2010	GW	077-09038	ORCHARD UNIT 19-15 (019OU)	PR

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 3/5/2026 at approximately 12:45, Compliance Inspector Matthew Morris conducted an on-site audit at QB ENERGY OPERATING LLC, ORCHARD UNIT-68S96W/19SWSE at Location ID #312723 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	911/(970)285-2615		
Corrective Action:		Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Concrete barriers installed at gas meter house.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Concrete barriers		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Summit Midstream		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:	Separator door is unsecured; open equipment poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to prevent wildlife entry.		Date: 03/16/2026

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		
Comment:	Corrosion near top weld of tank wall. No leaks present. Corrosion has stained the tank wall.				
Corrective Action:	Verify tank integrity and comply with CECMC Visual Mitigation Standards.			Date:	04/11/2026

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 283915 Type: WELL API Number: 077-09038 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						
		Check Dams				
		Ditches				
Gravel						
		Gravel				
Berms						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issue(s) were observed:</p> <p>1) Unsecured separator door; wildlife entry hazard                  2) Corrosion on condensate AST; staining</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	03/10/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404573875	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474569</a>
719500949	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474565">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7474565</a>