

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/16/2026

Submitted Date:

03/17/2026

Document Number:

717300830

**FIELD INSPECTION FORM**

Loc ID: 321408      Inspector Name: Maclaren, Joe      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER      State: CO      Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206878	WELL	SI	12/01/2025	GW	013-06373	TWIN CORNERS MC 4-5	EG
321330	LOCATION	AC			-	TWIN CORNERS-61N69W 4SEW	EG

**General Comment:**

ECMC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 206878 Type: WELL API Number: 013-06373 Status: SI Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 321330 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
Well (Twin Corners 4-5) is Temporarily Abandoned. WH flowline is shut in; wellhead valve and flowline manifold at inlet to HHS are OOSLAT. The facility/ tank battery is shut in (labeled SI); equipment/ flowlines OOSLAT.	maclarej	03/17/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300836	Tank battery and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483739">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483739</a>
717300837	WH flowline valve OOSLAT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483740">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7483740</a>