

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2026

Submitted Date:

03/17/2026

Document Number:

719001621

FIELD INSPECTION FORM

Loc ID: 333641 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216377	WELL	SI	01/01/2025	CBM	067-07983	EE PRESTON 1	SI
297331	WELL	PR	08/01/2020	CBM	067-09606	EE PRESTON 3	PR

General Comment:

Inspection Report Summary
On 3/17/26 | Inspector Charles Garcia conducted an desktop follow inspection.
Location: EE PRESTON 1, EE PRESTON 3
Operator: Simcoe LLC
API#: 067-07983
API#: 067-09606
County: LaPlata
DOC#719001523
FIR#404583258
CA RESOLVED

Inspected Facilities

Facility ID: 216377 Type: WELL API Number: 067-07983 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: SI
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/24/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 297331 Type: WELL API Number: 067-09606 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/24/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>LOCATION SIGN IN FRONT OF ELECTRIC PANEL NO WELL # ON WELL HEAD Corrective Action: Operator will post a sign at the entrance and well sign to an Oil and Gas Location that includes the Oil and Gas Location name PER 600 series rules CA RESOLVED PRODUCED WATER TANK LABEL AND PLACARD SUN DAMAGED NOT LEGIBLE SEE LOCATION PICTURES Corrective Action: Replace/install labels/placards per Rule 605 CA RESOLVED SEE LOCATION PICTURES FROM FIR DOC#404583258</p>	garciacr1	03/17/2026