

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2026

Submitted Date:

03/17/2026

Document Number:

719700517

FIELD INSPECTION FORM

Loc ID 305860 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282974	WELL	TA	08/01/2025	OW	123-23591	PETTINGER 34-2	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Blue TA tag posted. OOSLAT applied at separator(s).		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

Equipment:					corrective date
Type: Other	# 1				
Comment:	Wellhead: w/ Master, casing valves.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	
Type: Plunger Lift	# 0				
Comment:	Temporarily Abandoned TA. Equipment removed.				
Corrective Action:				Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.508207,-104.509877

Comment:	Centralized Battery serves 1 Location ID. (305860). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).		
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 282974 Type: WELL API Number: 123-23591 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted at wellsite(s).
OOSLAT applied at separator(s).
ECMC records last prod: 06/2025.

Form 4 on file. TA date: 08/08/2025. Approved.
DH-CIBP.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 01/27/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 03/17/2026 at approximately 11:34 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Location Name: PETTINGER-66N64W/2SWSE Location ID: 305860 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	03/17/2026
<p>This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID. (305860). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery formerly served 3 Location IDs. (305153, 305154, 305861). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700517 and/or Location ID #305860 for TA Well(s) info. B.) Field Audit Report doc. #719700519 and/or Location ID #305153 for PA Well(s) info. C.) Field Audit Report doc. #719700521 and/or Location ID #305861 for PA Well(s) info. D.) Field Audit Report doc. #719700523 and/or Location ID #305860 for Battery / Facility, Equipment info.</p>	evinsb	03/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700518	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7484373