

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/18/2026

Document Number:

697012568

FIELD INSPECTION FORM

Loc ID: 454131 Inspector Name: Peterson, Tom On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10819
Name of Operator: PRAIRIE OPERATING CO LLC
Address: 44 COOK STREET, SUITE 1000
City: DENVER State: CO Zip: 80206

Findings:

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@prairieopco.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
454125	WELL	PR	10/01/2025	OW	123-46419	Noble 14E5CS	PR
454126	WELL	PR	10/01/2025	OW	123-46420	Noble 11E5CS	PR
454127	WELL	PR	11/01/2025	OW	123-46421	Noble 5X-HNC-05-03-68	PR
454128	WELL	PR	10/01/2025	OW	123-46422	Noble 3E5NBAM	PR
454129	WELL	PR	10/01/2025	OW	123-46423	Noble 13E5NCS	PR
454130	WELL	PR	11/01/2025	OW	123-46424	NOBLE ST 5X-HNB-05-03-68	PR
454133	WELL	PR	10/01/2025	OW	123-46426	Noble 2E5NCBM	PR
454134	WELL	PR	10/01/2025	OW	123-46427	Noble 7E5NCBM	PR
454136	WELL	PR	10/01/2025	OW	123-46429	Noble 1E5NBAM	PR
454137	WELL	PR	11/01/2025	OW	123-46430	Noble 5X-HC-05-03-68	PR
487809	TANK BATTERY	AC	09/10/2024		-	NOBLE 3N68W5 Tank Battery	AC

General Comment:

This is a field audit of the scout card, related documents and the location.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	x 10, decals are attached to wellhead controllers.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease road entrance		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol system at compressor requires placards, see attached photos.		
Corrective Action:	Install sign to comply with Rule 605.	Date:	04/24/2026

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 3		
Comment:	Natural gas engines on gensets		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			

Corrective Action:		Date:	
Type: Gathering Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Pilots are on		
Corrective Action:		Date:	
Type: Pig Station	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 10		
Comment:	Electric motors on compressor, gas chiller, recirc pump, VRU'S and LACT's		
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Automation array ECD scrubbers, gensets, electrical systems, chemical systems in secondary containment, nitrogen system, sandtraps at wellheads, temporary 500 bbl trailer mount tank on secondary containment at sandtraps, propane tank, bulk lube oil storage in secondary containment with wildlife protection, five temporary 500 bbls trailer mount produced water tanks in lined secondary containment, recirc pump, gas chiller		
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Western Midstream calibration card is current.		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		

Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		
Comment: 533 bbls					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	STEEL AST		
Comment: 533 bbls					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	454125	Type:	WELL	API Number:	123-46419	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454126	Type:	WELL	API Number:	123-46420	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454127	Type:	WELL	API Number:	123-46421	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454128	Type:	WELL	API Number:	123-46422	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454129	Type:	WELL	API Number:	123-46423	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454130	Type:	WELL	API Number:	123-46424	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454133	Type:	WELL	API Number:	123-46426	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	454134	Type:	WELL	API Number:	123-46427	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR				Date:				
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454136 Type: WELL API Number: 123-46429 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 454137 Type: WELL API Number: 123-46430 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487809 Type: TANK API Number: - Status: AC Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Fail

Comment [Cellars are open on all of the wellheads, see attached photos. Conductors are open at two wellheads, see attached photos.](#)

Corrective Action [Comply with Role 1003.a.](#) Date **04/24/2026**

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Self Inspection	Pass	
Waddles	Pass	Tracking Pad	Pass			
Comment: <input type="text"/>						
Corrective Action: <input type="text"/>					Date: _____	
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Wednesday 3/18/2026 at approximately 10:00 hours I, Inspector Tom Peterson, conducted an on-site inspection at the Prairie Operating Noble 3N68W5 Pad in Weld County, Colorado.</p> <p>While there, I observed that the methanol system next to the compressor required all placards and the wellhead cellars and two conductors were open. During this inspection the following possible compliance issues were observed: Rule 605. with a corrective action date of 4/24/2026, Rule 1003.a. with a corrective action date of 4/24/2026. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	03/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697012569	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485761