

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2026

Submitted Date:

03/18/2026

Document Number:

716302052

FIELD INSPECTION FORM

Loc ID 307896 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
B ZECHES, GIENA		gzeches@ogrisop.com	All Inspections
BACA, DAVE	719-859-4066	dbaca@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259238	WELL	PR	09/04/2005	CBM	071-07211	HILL RANCH 22-12 V	PR
268803	PIT		07/25/2003		-	HILL RANCH 22-12V	

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5 & 6: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE FROM LEAKING DRIVEHEAD.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.		Date:
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 7: UNUSED EQUIPMENT (LARGE POLLY PIPE AND 2" POLLY PIPE AND EDGE OF PIT). PHOTO 8: UNUSED EQUIPMENT (PIPE ON EDGE OF PIT). PHOTO 9: UNUSED EQUIPMENT (HYDRALIC HOSE NEAR PRIME MOVER SOUND WALLS). PHOTO 10: UNUSED EQUIPMENT (2 PRIME MOVER HEADERS).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606.		Date: 03/24/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:

Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	30 BBL UNDER GROUND STEEL PRODUCED WATER TANK		
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	PHOTO 11: NO WILDLIFE PROTECTION INSTALLED ON 30 BBL INGROUND PRODUCED WATER TANK VENT.		
Corrective Action:	INSTALL BIRD PROTECTOR SCREEN OR OTHER DEVICE TO PROTECT WILDLIFE PER RULE 608b.(7).	Date:	03/24/2026

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259238 Type: WELL API Number: 071-07211 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 09/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 268803 Type: PIT API Number: - Status: _____ Insp. Status: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 268803 Lat: 37.066690 Long: -104.880024

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	268803	1121924	

ECMC Comments

Comment	User	Date
<p>THIS IS A FOLLOW-UP TO INSP.#698708255, ALL CA'S WHERE ADDRESSED WITH EXCEPTION OF LEAKING DRIVEHEAD, IMMEDIATE ACTION IS REQUIRED. ECMC Inspection Report Summary Date: 3/18/2026 Time: 15:21 Operator: Ogris Operating LLC.10758 Location: HILL RANCH 22-12V API# 05-071-07211 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: unused equipment, rule 606, 3/24/2026. mechanical condition of equipment, immediate action required. wildlife protection on vent, rule 608b.(7), 3/24/2026.follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	03/18/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302053	insp. photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485818