

Inspected Facilities

Facility ID: 273555 Type: WELL API Number: 071-08190 Status: PR Insp. Status: PR

Producing Well

Comment: [pr](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 279787 Type: WELL API Number: 071-08527 Status: PR Insp. Status: PR

Producing Well

Comment: [pr](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
THIS IS A FOLLOW-UP TO INSP. #716301885, BASED ON PHOTOS SUBMITTED IN FIRR #404577033 CA'S HAVE BEEN ADDRESSED.	beardslt	03/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716302043	OPERATOR PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485813
716302044	OPERATOR PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7485814