

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2026

Submitted Date:

03/12/2026

Document Number:

721100221

**FIELD INSPECTION FORM**

Loc ID: 438277    Inspector Name: Blair, Jamie    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46685  
 Name of Operator: KINDER MORGAN CO2 CO LLC  
 Address: 1001 LOUISIANA ST SUITE 1000  
 City: HOUSTON    State: TX    Zip: 77002

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	
General		CO2Source_Regulatory@kindermorgan.com	All SW field inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438279	WELL	TA	10/01/2017	CO2	033-06180	Doe Canyon 17	TA

**General Comment:**

On Monday, March 09, 2026 at 14:00 hrs, southwest compliance inspector James Blair performed an idle well compliance inspection and audit. One corrective action was observed. See attached photos.

**Location**

Overall Good:

**Signs/Marker:**

Type	OTHER		
Comment:	Well Location Signe near entrance at county road.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 24 Hour = 970-882-5522. Emergency = 911.

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:			corrective date
Other	# 1		
Comment:	wellhead. Disconnected. Marked as out of service.		
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:	accessible		
Corrective Action:		Date:	
Flow Line	# 1		
Comment:	disconnected. no out of service tag. Photos 4 and 5.		
Corrective Action:	OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b		Date: 04/09/2026

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 438279 Type: WELL API Number: 033-06180 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: MIT Date 8/10/2021.

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
No out-of-service tag. Photos 4 and 5. Comply with Rule 1105.b	blairj1	03/09/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404578375	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478709">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478709</a>
721100222	Photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478705">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478705</a>