

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2026

Submitted Date:

03/12/2026

Document Number:

721100227

**FIELD INSPECTION FORM**

Loc ID 427699 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LLC  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
General		CO2Source_Regulatory@kindermorgan.com	<a href="#">All SW field inspections</a>
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427711	WELL	TA	11/01/2018	CO2	033-06173	DOE CANYON 12	TA

**General Comment:**

On Tuesday, March 10, 2026 at 14:30 hrs, southwest compliance specialist Jamie Blair performed an idle well compliance inspection and audit. One corrective action was identified. See attached photos.

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Well location sign in SW corner by road. Photo 1.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-884-5522 = 24 Hour 911 = Emergency		Date:
Corrective Action:			
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	4 strand barbed wire and t post fence separating location from adjacent active agricultural field on north side.		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Other	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	accessible in well cellar.		
Corrective Action:			Date:
Type: Ancillary equipment	# 0		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	2" Flow line risers with guages and valves necked down with flanges to 1" lines valves, capped at ends. Behind yellow steel pipe barricades at entrance. There are no lock-outs or out of service tags. Photo 5.		
Corrective Action:	Comply with 1105.b.		Date: 04/13/2026
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 427711 Type: WELL API Number: 033-06173 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: MIT Date 4/18/2023

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: in well cellar.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Corrective action for unmarked flow line risers. See attached photos.</a>	blairj1	03/12/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404578376	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478711</a>
721100233	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478706">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7478706</a>