

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



300 bbl Condensate tank's paint is deteriorated with areas of rust corrosion.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



300 bbl Condensate tank's paint is deteriorated with areas of rust corrosion.



Flaking rust decay of tank's man hatch.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



80 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



200 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



No plug in separator glycol vessel.

No plug in separator glycol vessel.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



Unused cable inside of seperators fencing.



Unused cable inside of seperators fencing.

**TEP ROCKY MOUNTAIN LLC
FEDERAL-66S96W 35SESW
Location # 334595**



Above ground flowlines need protection to prevent damage.

Above ground flowlines need protection to prevent damage.

TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W 35SESW Location # 334595

