

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2026

Submitted Date:

03/19/2026

Document Number:

701104586

FIELD INSPECTION FORM

Loc ID: 334595 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211080	WELL	PR	08/30/1997	GW	045-06838	FEDERAL GR 24-35	EG
284297	WELL	PR	04/18/2006	GW	045-12136	FEDERAL GM 23-35	EG
284298	WELL	PR	04/18/2006	GW	045-12135	FEDERAL GM 324-35	EG
284299	WELL	PR	04/18/2006	GW	045-12134	FEDERAL GM 424-35	EG
284300	WELL	PR	04/18/2006	GW	045-12133	FEDERAL GM 524-35	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection

80 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.

200 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.

300 bbl Condensate tank's paint is deteriorated with areas of rust corrosion. Man hatch on tank has flacky rust decay.

Monitor, inspect, and repair rust and paint for integrity.

CA Date 4/4/26

Unused cable inside of separators fencing.

Comply with Rule 606

CA Date 4/4/26

2-2" flowlines from tank battery to separators need protection from possible traffic damage.

Comply with Rule 1102.e.(3)

CA Date 4/4/26

Both separator units have valves with out plugs on glycol vessels.

Plug valves to prevent possible release of glycol.

CA Date 4/4/26

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused cable inside of separators fencing.		
Corrective Action:	Comply with Rule 606		Date: 04/04/2026

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:					corrective date
Type: Flow Line	# 2				
Comment:	2-2" flowlines from tank battery to separators need protection from possible traffic damage.				
Corrective Action:	Comply with Rule 1102.e.(3)			Date:	04/04/2026
Type: Horizontal Heated Separator	# 5				
Comment:	Both units have valves with out plugs on glycol vessels.				
Corrective Action:	Plug valves to prevent possible release of glycol.			Date:	04/04/2026

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	

Comment:		80 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Inadequate						
Other (Content)							
Other (Capacity) 80 bbl							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate	Walls Sufficent		Base Sufficient		Adequate	
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	200 BBLs	STEEL AST				
Comment:		200 bbl Produced water tank's paint is deteriorated with areas of rust corrosion.				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Inadequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST				
Comment:		300 bbl Condensate tank's paint is deteriorated with areas of rust corrosion. Man hatch on tank has flacky rust decay.				Date:	
Corrective Action:		Monitor, inspect, and repair rust and paint for integrity.				Date: 04/04/2026	
<u>Paint</u>							
Condition	Inadequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance	
Comment:						Date:	

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211080 Type: WELL API Number: 045-06838 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284297 Type: WELL API Number: 045-12136 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284298 Type: WELL API Number: 045-12135 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284299 Type: WELL API Number: 045-12134 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 284300 Type: WELL API Number: 045-12133 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104587	Flowline integrity inspection 701104586 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7486281