

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2026

Submitted Date:

03/19/2026

Document Number:

701104591

FIELD INSPECTION FORM

Loc ID 324196 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|--------------------------------|--|
| Energy, QB | | ecmc.inspections@qb-energy.com | QB Inspection mail box |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 264267 | WELL | PR | 06/01/2022 | GW | 045-08195 | GMR 21-10B(21) | EG |

General Comment:

[Flowline Integrity Inspection and Tank Integrity Inspection](#)
Battery sign has incorrect API# for well.
Install sign to comply with Rule 605.e.
CA Date 4/4/26

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Battery sign has incorrect API# for well. | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 04/04/2026 |

| | | | |
|----------------------------------|-----|-------|-------|
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | Date: | _____ |

| | | | |
|---------------------------|-------|-------|--|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|--|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 264267 Type: WELL API Number: 045-08195 Status: PR Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 701104592 | Flowline integrity inspection 701104591 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7486641 |