

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2026

Submitted Date:

03/19/2026

Document Number:

719700529

FIELD INSPECTION FORM

Loc ID 310381 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292420	WELL	TA	05/14/2020	OW	123-26327	FOSS-USX AA 5-11	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	OOSLAT applied at well.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Undesirable plant species at wellsite(s). (Weeds). Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control undesirable plant species around wellsite(s). Comply with Rule 606.c. (14 days). See photo(s) #1, 2.		Date: <u>04/02/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 292420 Type: WELL API Number: 123-26327 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at well.
ECMC records last prod: 03/2017.

Form 4 on file. TA date: 11/30/2018. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 01/01/2017.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 03/06/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: Current Bhd Test date: 03/06/2026. (COGIS records).

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
This is a WELL audit. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.515428 / -104.469150 Abandoned Centralized Battery formerly served 2 Location IDs (310381, 306382). (Well(s): 1: Temporarily Abandoned TA;1: Plugged & Abandoned PA). Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700529 and/or Location ID #310381 for TA Well(s) info. B.) Field Audit Report doc. #719700531 and/or Location ID #306382 for PA Well(s) info.	evinsb	03/19/2026
CECMC Audit Report Synopsis: On THU 03/19/2026 at approximately 11:43 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: FOSS-USX AA-66N63W/5NESW Location ID: 310381 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry. While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.515428 / -104.469150 *CORRECTIVE ACTION ITEM(s): 1 1.) Refer to pg 2, "Good Housekeeping" section of this report. Routine audit. *Any Corrective Actions from prior audits that have not been addressed remain applicable.	evinsb	03/19/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700530	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7487197